Get the latest version from GitHub repo [here](#).

Building

1. Download GNU ARM Embedded 4.7 from [here](#)
2. Install on your Windows machine
3. Download CoIDE from [here](#)
4. Install, run and set compiler path to your GNU ARM directory
5. Double click on the firmware.coproj file to load project

Loading to flash

You can load the built binary image to STM32 flash via STlink interface and the SW debug connector on the UI board or simply using the USB utility and bootloader mode.